



Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
1	BOTTLE,Coolant Recovery	55116873AD	1	Yes		EX0		J U	74

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
1	BOTTLE,Coolant Recovery	55116873AE	1	Yes		EX0		J U	74
2	STUD,Double Ended,COOLANT RECOVERY BOTTLE TO BODY	06509092AA	1	No				J U	74
3	CAP	04596198	1	No		EX0		J U	74
4	HOSE,Overflow,Serviced With Recovery Bottle								
5	CLIP,Hose	52080133AB	1	No		EX0		J U	74

Note: Negative (-) item numbers indicate no illustration available.