



Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
------	-------------	-------------	-----	--------------	----------	--------	-------	------	------

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
1	WIRING,Front Door								
	Right	56048796AA	1	Yes				J	74
	Right	56048796AB	1	Yes				J	74
	Left	56048797AA	1	Yes				U	74
	Left	56048797AB	1	Yes				U	74
	Left	56048799AB	1	Yes				U	74
	Left	56048799AC	1	Yes				U	74
	Left	56048799AB	1	Yes				U	74
	Left	56048799AC	1	Yes				U	74
	Left	56048806AA	1	Yes				J	74
	Left	56048806AB	1	Yes				J	74
	Right	56048807AA	1	Yes				U	74
	Right	56048807AB	1	Yes				U	74
	Left	56048808AA	1	No				J	74
	Left	56048808AA	1	No				J	74
	Right	56048809AA	1	Yes				U	74
	Right	56048809AB	1	Yes				U	74
	Right	56048809AA	1	Yes				U	74
	Right	56048809AB	1	Yes				U	74
	Right	56048921AA	1	Yes				J	74
	Right	56048921AB	1	Yes				J	74
	Right	56048921AA	1	Yes				J	74
	Right	56048921AB	1	Yes				J	74
2	WIRING,Rear Door								
	Right or Left	56050067AJ	1	No				J U	74
	Right or Left	56050067AJ	1	No				J U	74
3	WIRING,Liftgate								

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
		56047788AC	1	Yes				J U	74
		56047788AD	1	Yes				J U	74
		56047788AE	1	Yes				J U	74
		56047788AF	1	Yes				J U	74
	[XAC]	56050879AC	1	Yes				J U	74
	[XAC]	56050879AD	1	Yes				J U	74
	[XAC]	56050879AE	1	Yes				J U	74

Note: Negative (-) item numbers indicate no illustration available.