

**For Electrical Connector Repair Information
Visit The Electrical Connector Website**

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
------	-------------	-------------	-----	--------------	----------	--------	-------	------	------

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
-1	STRAP,Tie,For Electrical Connector Repair Information Visit The Electrical Connector Website								
		04641780	1	No		EXL		J U	74
-2	CLIP,Wiring								
		52124121AA	2	No				J U	74

Note: Negative (-) item numbers indicate no illustration available.