

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
1	BEZEL,Instrument Panel,Center								
		1DE911AAAG	1	Yes				J U	74
		1DE911AAAH	1	Yes				J U	74
		1EA081AAAD	1	Yes				J U	74
		1EA091AAAD	1	Yes				J U	74
		1QX241AAAA	1	Yes				J U	74
		68036632AA	1	Yes				J U	74
		1EA081X9AD	1	Yes				J U	74
		1EA091X9AD	1	Yes				J U	74
		1EA081X9AE	1	Yes				J U	74
		1EA091X9AE	1	Yes				J U	74
		1DE912AAAG	1	Yes				J U	74
		1DE912AAAH	1	Yes				J U	74
		1EA082AAAD	1	Yes				J U	74
		1EA092AAAD	1	Yes				J U	74
		1QX242AAAA	1	Yes				J U	74
		68036632AA	1	Yes				J U	74
		1EA081X9AD	1	Yes				J U	74
		1EA091X9AD	1	Yes				J U	74
		1EA081X9AE	1	Yes				J U	74
		1EA091X9AE	1	Yes				J U	74
		1DE913AAAG	1	Yes				J U	74
		1DE913AAAH	1	Yes				J U	74
		1EA083AAAD	1	Yes				J U	74
		1EA093AAAD	1	Yes				J U	74
		1QX243AAAA	1	Yes				J U	74
		68036632AA	1	Yes				J U	74
		1EA081X9AD	1	Yes				J U	74


Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
		1EA091X9AD	1	Yes				J U	74
		1EA081X9AE	1	Yes				J U	74
		1EA091X9AE	1	Yes				J U	74
		1DE931AAAH	1	Yes				J U	74
		1DE931AAAI	1	Yes				J U	74
		1EA081AAAD	1	Yes				J U	74
		1EA091AAAD	1	Yes				J U	74
		68036632AA	1	Yes				J U	74
		68054221AA	1	Yes				J U	74
		1EA081X9AD	1	Yes				J U	74
		1EA091X9AD	1	Yes				J U	74
		1EA081X9AE	1	Yes				J U	74
		1EA091X9AE	1	Yes				J U	74
2	COVER,Knee Blocker								
	[D1]	1DS74BD1AC	1	No				J	74
	[J1]	1DS74BD1AC	1	No				J	74
	[DV]	1DS74XDVAC	1	No				J	74
	[J3]	1DS74ZJ3AC	1	No				J	74
	[D1]	1DS75BD1AC	1	No				U	74
	[J1]	1DS75BD1AC	1	No				U	74
	[DV]	1DS75XDVAC	1	No				U	74
	[J3]	1DS75ZJ3AC	1	No				U	74
3	GRILLE,Defroster								
	Right,[D1]	1DQ54XDVAA	1	No				J U	74
	Right,[DV]	1DQ54XDVAA	1	No				J U	74
	Right,[J1]	1DQ54ZJ8AA	1	No				J U	74
	Right,[J3]	1DQ54ZJ8AA	1	No				J U	74
	Left,[D1]	1DQ55XDVAA	1	No				J U	74





Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
	Left,[DV]	1DQ55XDVAA	1	No				J U	74
	Left,[J1]	1DQ55ZJ8AA	1	No				J U	74
	Left,[J3]	1DQ55ZJ8AA	1	No				J U	74
4	BIN,Instrument Panel								
	[D1][XA8]	1EJ29BD1AD	1	Yes				J U	74
	[D1][XA8]	1EJ29BD1AE	1	Yes				J U	74
	[D1][XA8]	1EJ29BD1AF	1	Yes				J U	74
	[J1][XA8]	1EJ29BD1AD	1	Yes				J U	74
	[J1][XA8]	1EJ29BD1AE	1	Yes				J U	74
	[J1][XA8]	1EJ29BD1AF	1	Yes				J U	74
	[DV][XA8]	1EJ29XDVAD	1	Yes				J U	74
	[DV][XA8]	1EJ29XDVAE	1	Yes				J U	74
	[DV][XA8]	1EJ29XDVAF	1	Yes				J U	74
	[J3][XA8]	1EJ29ZJ3AD	1	Yes				J U	74
	[J3][XA8]	1EJ29ZJ3AE	1	Yes				J U	74
	[J3][XA8]	1EJ29ZJ3AF	1	Yes				J U	74
	[D1][XAM,XAP]	1EJ30BD1AD	1	Yes				J U	74
	[D1][XAM,XAP]	1EJ30BD1AE	1	Yes				J U	74
	[D1][XAM,XAP]	1EJ30BD1AF	1	Yes				J U	74
	[J1][XAM,XAP]	1EJ30BD1AD	1	Yes				J U	74
	[J1][XAM,XAP]	1EJ30BD1AE	1	Yes				J U	74
	[J1][XAM,XAP]	1EJ30BD1AF	1	Yes				J U	74
	[DV][XAM,XAP]	1EJ30XDVAD	1	Yes				J U	74
	[DV][XAM,XAP]	1EJ30XDVAE	1	Yes				J U	74
	[DV][XAM,XAP]	1EJ30XDVAF	1	Yes				J U	74
5	PANEL,Instrument Panel Closeout								
		55116775AL	1	No				J	74
		55116777AK	1	No				U	74

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
6	PLUG,Instrument Panel								
	[DV]	5JN32XDVAD	1	No				J U	74
	[J3]	5JN32ZJ8AD	1	No				J U	74
7	COVER,Steering Column Gap								
	[D1]	1DE99BD1AC	1	Yes				J U	74
	[D1]	1DE99BD1AD	1	Yes				J U	74
	[J1]	1DE99BD1AC	1	Yes				J U	74
	[J1]	1DE99BD1AD	1	Yes				J U	74
	[DV]	1DE99XDVAC	1	Yes				J U	74
	[DV]	1DE99XDVAD	1	Yes				J U	74
	[J3]	1DE99ZJ3AC	1	Yes				J U	74
	[J3]	1DE99ZJ3AD	1	Yes				J U	74
8	PANEL,Instrument Panel Closeout								
		55116780AL	1	No				J	74
		55116782AK	1	No				U	74
9	BEZEL,Ignition Switch								
	[D1]	1DS72BD1AC	1	No				J	74
	[J1]	1DS72BD1AC	1	No				J	74
	[DV]	1DS72XDVAC	1	No				J	74
	[J3]	1DS72ZJ3AC	1	No				J	74
	[D1]	1DS73BD1AC	1	No				U	74
	[J1]	1DS73BD1AC	1	No				U	74
	[DV]	1DS73XDVAC	1	No				U	74
	[J3]	1DS73ZJ3AC	1	No				U	74
10	BEZEL,Cluster								
	[D1]	1DE89XDVAB	1	Yes				J	74
	[D1]	1DE89XDVAC	1	Yes				J	74

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
	[DV]	1DE89XDVAB	1	Yes				J	74
	[DV]	1DE89XDVAC	1	Yes				J	74
	[J1]	1DE89ZJ8AB	1	Yes				J	74
	[J1]	1DE89ZJ8AC	1	Yes				J	74
	[J3]	1DE89ZJ8AB	1	Yes				J	74
	[J3]	1DE89ZJ8AC	1	Yes				J	74
	[D1]	1DE90XDVAB	1	Yes				U	74
	[D1]	1DE90XDVAC	1	Yes				U	74
	[DV]	1DE90XDVAB	1	Yes				U	74
	[DV]	1DE90XDVAC	1	Yes				U	74
	[J1]	1DE90ZJ8AB	1	Yes				U	74
	[J1]	1DE90ZJ8AC	1	Yes				U	74
	[J3]	1DE90ZJ8AB	1	Yes				U	74
	[J3]	1DE90ZJ8AC	1	Yes				U	74
11	GRILLE,Instrument Panel Speaker								
	Right,[D1]	5KB00XDVAH	1	Yes				J U	74
	Right,[D1]	5KB00XDVAI	1	Yes				J U	74
	Right,[D1]	5KB00XDVAJ	1	Yes				J U	74
	Right,[D1]	5KB00XDVAK	1	Yes				J U	74
	Right,[DV]	5KB00XDVAH	1	Yes				J U	74
	Right,[DV]	5KB00XDVAI	1	Yes				J U	74
	Right,[DV]	5KB00XDVAJ	1	Yes				J U	74
	Right,[DV]	5KB00XDVAK	1	Yes				J U	74
	Right,[J1]	5KB00ZJ8AH	1	Yes				J U	74
	Right,[J1]	5KB00ZJ8AI	1	Yes				J U	74
	Right,[J1]	5KB00ZJ8AJ	1	Yes				J U	74
	Right,[J1]	5KB00ZJ8AK	1	Yes				J U	74
	Right,[J3]	5KB00ZJ8AH	1	Yes				J U	74

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
	Right,[J3]	5KB00ZJ8AI	1	Yes				J U	74
	Right,[J3]	5KB00ZJ8AJ	1	Yes				J U	74
	Right,[J3]	5KB00ZJ8AK	1	Yes				J U	74
	Left,[D1]	5KB01XDVAH	1	Yes				J U	74
	Left,[D1]	5KB01XDVAI	1	Yes				J U	74
	Left,[D1]	5KB01XDVAJ	1	Yes				J U	74
	Left,[D1]	5KB01XDVAK	1	Yes				J U	74
	Left,[DV]	5KB01XDVAH	1	Yes				J U	74
	Left,[DV]	5KB01XDVAI	1	Yes				J U	74
	Left,[DV]	5KB01XDVAJ	1	Yes				J U	74
	Left,[DV]	5KB01XDVAK	1	Yes				J U	74
	Left,[J1]	5KB01ZJ8AH	1	Yes				J U	74
	Left,[J1]	5KB01ZJ8AI	1	Yes				J U	74
	Left,[J1]	5KB01ZJ8AJ	1	Yes				J U	74
	Left,[J1]	5KB01ZJ8AK	1	Yes				J U	74
	Left,[J3]	5KB01ZJ8AH	1	Yes				J U	74
	Left,[J3]	5KB01ZJ8AI	1	Yes				J U	74
	Left,[J3]	5KB01ZJ8AJ	1	Yes				J U	74
	Left,[J3]	5KB01ZJ8AK	1	Yes				J U	74
12	GRILLE,Lower								
	Right,[D1]	1FC54BD1AB	1	Yes				J U	74
	Right,[D1]	1FC54BD1AC	1	Yes				J U	74
	Right,[J1]	1FC54BD1AB	1	Yes				J U	74
	Right,[J1]	1FC54BD1AC	1	Yes				J U	74
	Right,[DV]	1FC54XDVAB	1	Yes				J U	74
	Right,[DV]	1FC54XDVAC	1	Yes				J U	74
	Right,[J3]	1FC54ZJ3AB	1	Yes				J U	74
	Right,[J3]	1FC54ZJ3AC	1	Yes				J U	74

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
	Left,[D1]	1FC55BD1AB	1	Yes				J U	74
	Left,[D1]	1FC55BD1AC	1	Yes				J U	74
	Left,[J1]	1FC55BD1AB	1	Yes				J U	74
	Left,[J1]	1FC55BD1AC	1	Yes				J U	74
	Left,[DV]	1FC55XDVAB	1	Yes				J U	74
	Left,[DV]	1FC55XDVAC	1	Yes				J U	74
	Left,[J3]	1FC55ZJ3AB	1	Yes				J U	74
	Left,[J3]	1FC55ZJ3AC	1	Yes				J U	74
13	POWER OUTLET	04793554AC	1	No				J U	74
14	BASE,Cigar Lighter	04685590	1	No				J U	74
15	CAP,Power Outlet	04685666AB	1	Yes				J U	74
15	CAP,Power Outlet	04685668AC	1	Yes				J U	74
16	RING,Cigar Lighter Mounting	04793555	1	No				J U	74
17	MOUNT,Power Outlet	04685668AA	1	No				J U	74
18	BEZEL,Sensor								
	[D1]	1EJ31XDVAC	1	Yes				J U	74
	[D1]	1EJ31XDVAD	1	Yes				J U	74
	[DV]	1EJ31XDVAC	1	Yes				J U	74
	[DV]	1EJ31XDVAD	1	Yes				J U	74
	[J1]	1EJ31ZJ8AC	1	Yes				J U	74
	[J1]	1EJ31ZJ8AD	1	Yes				J U	74
	[J3]	1EJ31ZJ8AC	1	Yes				J U	74
	[J3]	1EJ31ZJ8AD	1	Yes				J U	74
-19	OUTLET,Air Conditioning & Heater,Outboard								
	Right,[D1]	1BL761DVAB	1	Yes				J	74
	Right,[D1]	1BL76XDVAC	1	Yes				J	74

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
	Right,[DV]	1BL761DVAB	1	Yes				J	74
	Right,[DV]	1BL76XDVAC	1	Yes				J	74
	Right,[J1]	1BL761J8AB	1	Yes				J	74
	Right,[J1]	1BL76ZJ8AC	1	Yes				J	74
	Right,[J3]	1BL761J8AB	1	Yes				J	74
	Right,[J3]	1BL76ZJ8AC	1	Yes				J	74
	Left,[D1]	1BL771DVAB	1	Yes				J	74
	Left,[D1]	1BL77XDVAC	1	Yes				J	74
	Left,[DV]	1BL771DVAB	1	Yes				J	74
	Left,[DV]	1BL77XDVAC	1	Yes				J	74
	Left,[J1]	1BL771J8AB	1	Yes				J	74
	Left,[J1]	1BL77ZJ8AC	1	Yes				J	74
	Left,[J3]	1BL771J8AB	1	Yes				J	74
	Left,[J3]	1BL77ZJ8AC	1	Yes				J	74

Note: Negative (-) item numbers indicate no illustration available.