



Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
1	WASHER								

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
		05175360AA	1	No		EXL		J U	74
2	SHAFT,Balance								
		05175346AA	1	No		EXL		J U	74
3	COVER,Balance Shaft								
		05175362AB	1	Yes		EXL		J U	74
		68166521AA	1	Yes		EXL		J U	74
4	BOLT								
		06104004AA	1	No		EX0		J U	74
5	BOLT,6 Lobe External Head,M6X1.00X16.00								
		06104005AA	1	No		EXL		J U	74

Note: Negative (-) item numbers indicate no illustration available.