



Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
1	AIR BAG,Side Curtain								

Item	Description	Part Number	Qty	Supersedence	Tech Tip	Engine	Trans	Line	Body
	Right	52029296AG	1	Yes				J U	74
	Right	52029296AH	1	Yes				J U	74
	Left	52029297AG	1	Yes				J U	74
	Left	52029297AH	1	Yes				J U	74
2	SCREW,Hex Head,M6X1.00X26.50								

Note: Negative (-) item numbers indicate no illustration available.